



QUALITY... PLAIN & SIMPLE®

Throttle Cable Bracket & Return Springs Installation Instructions

Stainless Steel Carburetor Bracket and Return Springs
Part# SRK4000


General Installation Notes:

Please read instructions completely before beginning installation.

If you have any questions please don't hesitate to call.

Throttle Cable Bracket & Return Springs Installation

1. Install throttle cable bracket to rear carburetor base mounting bolt
2. Tear drop will be held in place by Kickdown Connector
3. Align bend parallel to carburetor base
4. Tighten set screw until it touches the carburetor base and lock down with lock nut



Building American Quality... With A Lifetime Warranty!

10924 Murdock Dr. • Knoxville, TN 37932
Toll Free 1-877-469-7440 • (865) 966-2269 • FAX (865) 671-1999
tech@lokar.com • www.lokar.com